

Basic Vehicle Condition Guide

Report ID: 19,848,191


Version: 1

Created: 01 Nov 2019

Make: Model: NV350 Nissan **Body Style:** Wagon Year: 2014 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 16 Oct 2020 140,600 Kms 19848191 VIN: 7AT0DH8RX19013745 **Next Service:** Unknown **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comment	<u>S</u>
Seats	Drivers seat worn
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

9 seater

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Murray Craig Date: 01 Nov 2019

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
d depth	of tyre	es)
9		mm
5		
9		mm
ğ		mm mm
Ğ)	-
Ğ)	mm
Ğ))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
\(\frac{\chi}{\chi} \)))	mm
V V V V V V V V V V V V V V V V V V V))	mm
V V V V V V V V V V V V V V V V V V V))	mm
	V V V V V	v v v v v v v depth of tyre

Signature: