



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,848,923
Version:	2
Created:	06 Nov 2019

Make:	Mazda	Body Style:	SUV
Model:	Premacy	VIN:	7AT0C133X19105892
Year:	2010	Odometer:	115,440 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good					
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good					
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good						
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good						
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	Wheels and Tyres		85	R/H Mirror	Good						
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	4.0	mm	86	L/H Mirror	Good							
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>4.0</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	4.0	mm	87	L/F Guard	Good							
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>63</td> <td>Left Rear</td> <td>4.0</td> <td>mm</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	63	Left Rear	4.0	mm	88	R/F Guard	Good							
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>4.0</td> <td>mm</td> <td>89</td> <td>L/H Doors</td> <td>Good</td>	64	Right Rear	4.0	mm	89	L/H Doors	Good							
10	Rear Reflectors	✓	40	Gearbox (Manual)	✓ <td>65</td> <td>Spare</td> <td>Yes</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	65	Spare	Yes	90	R/H Doors	Good								
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	66	Tools	✓	91	L/H Sill	Good								
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	Interior		67	AC Operation	✓	92	R/H Sill	Good						
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		68	Heater Fan	✓	69	Seatbelts	✓	93	Boot/Tail Gate	Good					
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	70	Horn	✓	71	Seat Heaters	•	94	Front Bumper	Good			
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	95	Rear Bumper	Good		
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	74	Seats	Good	75	Carpets	Good	96	Roof	Good			
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	49	Number of Keys	1	76	Panels	Good	77	Dashboard	Good	97	Bonnet	Good		
18	Odometer	✓	Engine		50	Oil Level	✓ <td>51</td> <td>Smokes and Fumes</td> <th>✓<td>52</td><td>Performance</td><th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th></th>	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>98</td><td>Fuel Cap</td><th>✓</th></th>	53	Noise	✓ <td>98</td> <td>Fuel Cap</td> <th>✓</th>	98	Fuel Cap	✓
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>54</td><td>Starter Motor</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>54</td><td>Starter Motor</td><th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th></th>	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>99</td><td>Mud Flaps</td><th>✓</th></th>	54	Starter Motor	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓		
20	Fuel Gauge	✓	52	Performance	✓ <td>99</td> <td>WOF</td> <th>✓</th>	99	WOF	✓											
21	Wipers Front/Rear	✓	53	Noise	✓ <td></td> <td></td> <td></td>														
22	Window Opener FL	✓	54	Starter Motor	✓ <td></td> <td></td> <td></td>														
23	Window Opener FR	✓																	
24	Window Opener RL	✓																	
25	Window Opener RR	✓																	
26	Rear View Mirrors	✓																	
27	Radio (Basic Test Only)	✓																	
28	CD (Basic Test Only)	✓																	
29	Boot Open Switch	✓																	

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	27 Oct 2019
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--