



This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,849,328
Version:	2
Created:	17 Nov 2019

Make:	Subaru	Body Style:	Wagon
Model:	Legacy	VIN:	7AT0GF0BX19012724
Year:	2013	Odometer:	108,090 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System			78	Under Carriage	Good	Exterior	
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation		•
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)		Good
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)		Good
4	High Stop Light	✓	Transmission and Drive			Suspension			82	Side Windows (no chips)		Good
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades		Good
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade		Good
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	Wheels and Tyres			
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	4 mm	85	R/H Mirror		Good
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	4 mm	86	L/H Mirror		Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	6 mm	87	L/F Guard	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	6 mm	88	R/F Guard	Good	
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	89	L/H Doors	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	90	R/H Doors	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior			91	L/H Sill	Good	
15	Number Plate Light	✓	Brakes			67	AC Operation	✓	92	R/H Sill	Good	
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	95	Rear Bumper	Good	
19	Rev Counter	✓	Keys and Locking			71	Seat Heaters	•	96	Roof	Good	
20	Fuel Gauge	✓	47	Central Locking	•	72	Sun Visors	✓	97	Bonnet	Good	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓	
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Average	99	Mud Flaps	✓	
23	Window Opener FR	✓	Engine			75	Carpets	Average	100	WOF	✓	
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Average				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Average				
26	Rear View Mirrors	✓	52	Performance	✓							
27	Radio (Basic Test Only)	✓	53	Noise	✓							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓							
29	Boot Open Switch	✓										

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Andrew Loach	Date:	17 Nov 2019
<b>I have read and understood this condition guide:</b>			
Name:		Signature:	