

Report ID: 19,851,452 Version: 2 06 Nov 2019 Created:

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003	Registration:	EKL624	Reg Expiry:	13 Dec 2019	Engine			
WoF Expiry:	20 Nov 2020	Odometer:	132,399 Kms	Good No:	19851452	Oil level	~		
VIN:	7A8C12H0707239189	Next Service:	135233	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		S SC S		D	Performance	~		
Key:	B	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	w bla			715	HIV	Operation	~		
PT = paint defe		r I		$\left[\left(\right) \right]$	7014	Noise	~		
C = crack					D SC	Clutch			~
P = pin dent	HIP				74116	CV joints	~		
* = decals	s sc gle			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts W S D S W						Performance	~		
Body Incr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Minor stone chips front screen. Dents left sill. No cargo blind. Right door mirror housing broken						Tyres (lowest observed tread	depth	oftyre	ès)
winderstelle einpartone sereen, benea iereanie no eargo binde night door mintor nousing broken						Left front 4.0 m			mm
						Right front	5.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpote	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	iu					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism. Timing Chair						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			2
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 01 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: