



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,852,485
Version:	1
Created:	08 Nov 2019

Make:	Nissan	Body Style:	Van
Model:	NV200	VIN:	7AT0DH8MX19082411
Year:	2015	Odometer:	72,123 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good		
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good		
3	Tail Lights	✓	33	Window Lock Switch	•	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good			
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good			
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <th>✓<td>60</td><td>Shock Absorbers</td><th>✓<td>85</td><td>R/H Mirror</td><td>Good</td></th></th>	36	Clutch	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>85</td><td>R/H Mirror</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>85</td> <td>R/H Mirror</td> <td>Good</td>	85	R/H Mirror	Good		
6	Front Left Indicators	✓	37	CV Joints	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>4</td> <td>mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	Wheels and Tyres		61	Left Front	4	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	38	Wheel Bearing	✓ <td>62</td> <td>Right Front</td> <td>4</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	4	mm	63	Left Rear	6	mm	87	L/F Guard	Good
8	Rear Left Indicators	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	64	Right Rear	6	mm	65	Spare	Yes	88	R/F Guard	Good	
9	Reversing Lights	✓	40	Gearbox (Manual)	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>89</td> <td>L/H Doors</td> <td>Good</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	66	Tools	✓	89	L/H Doors	Good	90	R/H Doors	Good		
10	Rear Reflectors	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	91	L/H Sill	Good	92	R/H Sill	Good		
11	Hazard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	68	Heater Fan	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	93	Boot/Tail Gate	Good	94	Front Bumper	Good		
12	Courtesy Lights	✓	43	Replaced at (odometer reading)		69	Seatbelts	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good		
13	Dashboard Lights	✓	Brakes		44	Front Brakes	✓ <td>70</td> <td>Horn</td> <th>✓<td>97</td><td>Bonnet</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	70	Horn	✓ <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	97	Bonnet	Good	98	Fuel Cap	✓
14	Dashboard Dimmer Switch	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>71</td><td>Seat Heaters</td><td>•</td><td>99</td><td>Mud Flaps</td><th>✓</th></th>	46	Handbrake	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>99</td> <td>Mud Flaps</td> <th>✓</th>	71	Seat Heaters	•	99	Mud Flaps	✓		
15	Number Plate Light	✓	Keys and Locking		47	Central Locking	✓ <td>72</td> <td>Sun Visors</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	72	Sun Visors	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓			
16	Dashboard Warning Lights	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td></td><td></td><td></td></th>	49	Number of Keys	2	73	Sun Visors Lights/Mirrors	✓ <td></td> <td></td> <td></td>					
17	Speedo	✓	Engine		50	Oil Level	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td></td> <td></td> <td></td>	74	Seats	Good						
18	Odometer	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td></td><td></td><td></td></th>	52	Performance	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td></td> <td></td> <td></td>	75	Carpets	Good					
19	Rev Counter	•	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>76</td><td>Panels</td><td>Good</td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td></td> <td></td> <td></td>	76	Panels	Good					
20	Fuel Gauge	✓							77	Dashboard	Good					
21	Wipers Front/Rear	✓														
22	Window Opener FL	✓														
23	Window Opener FR	✓														
24	Window Opener RL	•														
25	Window Opener RR	•														
26	Rear View Mirrors	✓														
27	Radio (Basic Test Only)	✓														
28	CD (Basic Test Only)	•														
29	Boot Open Switch	✓														

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	John Lindsay	Date:	08 Nov 2019
---------------	--------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--