

Report ID: 19,854,277 Version: 2 14 Nov 2019 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	1996	Registration:	EGA255	Reg Expiry:	09 Nov 2019	Engine				
WoF Expiry:	21 Nov 2019	Odometer:	168,071 Kms	Good No:	19854277	Oil level	V			
VIN:	7A8H6070707139043	Next Service:	147000	Service Histor	<b>y:</b> No	Smoke & fumes	V			
						Performance	V			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
	S PT W				S D W	Performance	V			
Key:	S PT W	-0	S D PT	-	SDW	Radiator / Hoses (visual)	V			
S = scratch						Transmission				
D = dent R = rust	D PT SC W			715	S D PT W	Operation	~			
PT = paint defe	ect NP			$\left[ \left( \right) \right]$		Noise	r			
C = crack					PT SC	Clutch			~	
P = pin dent	HIG				74114	CV joints	V			
* = decals	s sc w 916			-No-	ALC S	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs D R SC W S D W S D						Performance	~			
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)	
								mm		
						Right front		5	mm	
						Left rear		3	mm	
Conditions During Body Inspection: Dry						Right rear			mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension				
Engine oil leak						Suspension performance	~			
outer cv bo	ots leaking grease					Steering performance	· ·			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	left front s	eat stains				Head lights	~			
	mate stain	~d				Tail lights	~			
Carpets	mats stain	cu				Indicators	~			
Panels	Average					Dashboard warning lights	~			
	A					Wipers (front & rear)	~			
Dashboa	rd Average					Window winder FL	~			
	I					Window winder FR	~			
General Comments						Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	V			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2	L	I	
Road Conditions During Test Drive: Dry						Central locking	· ·			
						Remote locking			~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~	
L										
Inspected by: John Lindsay Date: 14 Nov 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....