



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,855,555
Version:	1
Created:	08 Nov 2019

Make:	Subaru	Body Style:	SUV
Model:	Forester	VIN:	7AT0GF17X19035209
Year:	2009	Odometer:	86,427 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		•					
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good						
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	7.0	mm	84	Rear Wiper Blade	Good			
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	7.0	mm	63	Left Rear	7.0	mm	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	64	Right Rear	7.0	mm	65	Spare	Yes	86	L/H Mirror	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	66	Tools	✓	67	AC Operation	✓	87	L/F Guard	Good			
10	Rear Reflectors	•	40	Gearbox (Manual)	• <th colspan="2">Interior</th> <td>68</td> <td>Heater Fan</td> <th>✓</th> <td>69</td> <td>Seatbelts</td> <th>✓</th> <td>88</td> <td>R/F Guard</td> <td>Good</td>	Interior		68	Heater Fan	✓	69	Seatbelts	✓	88	R/F Guard	Good	
11	Hazard Lights	✓	41	Engine Timing	Cambelt	70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	89	L/H Doors	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	No	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	75	Carpets	Good	90	R/H Doors	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		76	Panels	Good	77	Dashboard	Good	91	L/H Sill	Good	92	R/H Sill	Good
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good	95	Rear Bumper	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	96	Roof	Good	97	Bonnet	Good	98	Fuel Cap	✓
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓	48	Remote Locking	✓	49	Number of Keys	1	99	Mud Flaps	✓	
17	Speedo	✓	48	Remote Locking	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	100	WOF	✗	
18	Odometer	✓	49	Number of Keys	1	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓			
19	Rev Counter	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓							
20	Fuel Gauge	✓	50	Oil Level	✓	52	Performance	✓									
21	Wipers Front/Rear	✓	51	Smokes and Fumes	✓	53	Noise	✓									
22	Window Opener FL	✓	52	Performance	✓	54	Starter Motor	✓									
23	Window Opener FR	✓	53	Noise	✓												
24	Window Opener RL	✓	54	Starter Motor	✓												
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✗															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Mathew Varghese	Date:	03 Nov 2019
I have read and understood this condition guide:			
Name:		Signature:	