



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,855,564
Version:	2
Created:	06 Oct 2020

Make:	Mitsubishi	Body Style:	SUV
Model:	Outlander	VIN:	7AT0CJ3MX19102437
Year:	2014	Odometer:	93,877 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	✓	80	Front Windscreen (no chips)	Good
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58 <td>Suspension Performance</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	Suspension Performance	✓	83	Front Wiper Blades	Good	
4	High Stop Light	✓	Transmission and Drive		34 <td>Operation</td> <th>✓</th> <td>59</td> <td>Steering Performance</td> <th>✓</th> <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	Operation	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good	
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		85	R/H Mirror	Good	
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	7.0	mm	86	L/H Mirror	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	7.0	mm	87	L/F Guard	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	63	Left Rear	5.0	mm	88	R/F Guard	Good		
9	Reversing Lights	✓	39	Wheel Balance	✓	64	Right Rear	5.0	mm	89	L/H Doors	Good		
10	Rear Reflectors	•	40	Gearbox (Manual)	•	65	Spare	N/A	66	Tools	✓	90	R/H Doors	Good
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	68	Heater Fan	✓	91	L/H Sill	Good
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓	70	Horn	✓	92	R/H Sill	Good
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		71	Seat Heaters	✓	72	Sun Visors	✓	93	Boot/Tail Gate	Good
14	Dashboard Dimmer Switch	✓	Brakes		44 <td>Front Brakes</td> <th>✓</th> <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓</th> <td>74</td> <td>Seats</td> <td>Good</td>	Front Brakes	✓	73	Sun Visors Lights/Mirrors	✓	74	Seats	Good	
15	Number Plate Light	✓	45	Rear Brakes	✓	46	Handbrake	✓	Interior		75	Carpets	Good	
16	Dashboard Warning Lights	✓	Keys and Locking		47 <td>Central Locking</td> <th>✓</th> <td>76</td> <td>Panels</td> <td>Good</td> <td>77</td> <td>Dashboard</td> <td>Good</td>	Central Locking	✓	76	Panels	Good	77	Dashboard	Good	
17	Speedo	✓	48	Remote Locking	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	
18	Odometer	✓	49	Number of Keys	1	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓
19	Rev Counter	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	
20	Fuel Gauge	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓
21	Wipers Front/Rear	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓
22	Window Opener FL	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓			
23	Window Opener FR	✓	53	Noise	✓									
24	Window Opener RL	✓	54	Starter Motor	✓									
25	Window Opener RR	✓												
26	Rear View Mirrors	✓												
27	Radio (Basic Test Only)	✓												
28	CD (Basic Test Only)	✓												
29	Boot Open Switch	✓												

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Mathew Varghese	Date:	03 Nov 2019
I have read and understood this condition guide:			
Name:		Signature:	