

Report ID: 19,857,031 Version: 2 11 Nov 2019 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JMM187	Reg Expiry:	10 Dec 2019	Engine	1		I
WoF Expiry:	08 Nov 2020	Odometer:	134,554 Kms	Good No:	19857031	Oil level	~		
VIN:	JM0BM547810205369	Next Service:	144,000kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	PT P	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HD				세비	CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S D S P						Performance	~		
Dody Inc		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	depth	of tyre	es)
Rear badge letter missing Front bumper misaligned									mm
Windscreen stone chips 1 remote key fail						Right front		3	mm
T remote ke						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front whee	l drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
L						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
									1
Inspected by: Mathew Varghese Date: 11 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: