

Report ID: 19,857,763 Version: 2 15 Nov 2019 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	CNP598	<b>Reg Expiry:</b>	28 Jul 2020	Engine			
WoF Expiry:	13 Nov 2020	Odometer:	217,584 Kms	Good No:	19857763	Oil level	~		
VIN:	JHLRD77505C202032	Next Service:	221000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	lis can be arranged to		inarge.	Coolant condition	~		
	S P W		SDW SDR		S D	Performance	~		
<b>Key:</b> S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sc w			10	SW.	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					S D PT SC	Clutch	~		
P = pin dent	DRSC DR				24116	CV joints	~		
* = decals SC = stone chips						Wheel bearings	<		
W = significant scuffs						Brakes			
	S W		S D S D	W	S P	Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.0	mm
						Right front	5.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments driver seat worn						Electrical / Accessories			
Seats	driver seat	worn				Head lights	~		
Carpets	driver mat	worn, front mat	s stained			Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Machanism	Time in a f	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: John Lindsay Date: 04 Nov 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....