

Basic Vehicle Condition Guide

Report ID: 19,860,518


Version: 2

Created: 07 Nov 2019

Make: Model: Mitsubishi Colt **Body Style:** Hatchback Year: 2006 Registration: DSZ523 Reg Expiry: 26 Nov 2019 WoF Expiry: **Odometer:** 20 May 2020 138,484 Kms **Good No:** 19860518 VIN: **Next Service:** 7A8CJ0X0707303371 148,400 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chip on front windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Average | | |
| Dashboard | Average | | |

| Canaral | Commonts |
|---------|----------|
| Generai | Comments |

Fuel pump noisy

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

07 Nov 2019 Inspected by: Mathew Varghese Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|-----------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | V | | |
| Noise | ~ | | |
| Cooling System | | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | ' | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | 1 | ı | 1 |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 5 | mm |
| Right front | 6 | | mm |
| Left rear | | 2 | mm |
| Right rear | | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | <u> </u> | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | <u></u> | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) | \(\triangle \) | | |
| Window winder FL | ., | | |
| Window winder FR | <i>v</i> | | |
| | | | |
| Window winder RL | V | | |
| Window winder RR | V | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | ı |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

Signature: