

## **Basic Vehicle Condition Guide**

Report ID: 19,860,659


Version: 1

Created: 06 Nov 2019

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2006 Registration: **DDQ830** Reg Expiry: 31 Jan 2020 WoF Expiry: **Odometer:** 08 Oct 2020 133,496 Kms **Good No:** 19860659 VIN: KMHJN81DR6U32157 Next Service: 133400 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

**Conditions During Body Inspection:** Dry

## **Under Carriage & Under Bonnet Inspection Comments**

Both front tie rod end play Engine oil leaks All tyre low

Interior (	Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Good

## **General Comments**

AWD

AC not working ESP light on

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes Kms: 92,775

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		-	1
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	2	.0	mm
Right front	2.0		mm
Left rear	2.0 mm		mm
Right rear	2	2.0 mm	
Spare		Yes	
Suspension			
Suspension performance	<i>V V</i>		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		1	1
Operation		~	
Electrical / Accessories		1	1
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights		~	
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V V V V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	-	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

**Eddie Marsters** 

Name: .....

Signature: .....

06 Nov 2019