

	haulo (basic test offiy)	V	
	CD (basic test only)	~	
	Number of keys	1	
Road Conditions During Test Drive: Dry	Central locking	~	
	Remote locking	~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		
Evidence of Cam Belt Replacement:YesKms:273,330	Reversing camera		
		10	

Inspected by: Donovan Matara

Date: 06 Nov 2019

I have read and understood this condition guide.

Name:

Signature:

レレ