

Report ID: 19,861,459 Version: 1 08 Nov 2019 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1997		CAA792	Reg Expiry:	01 Jan 2020	Engine	1		
WoF Expiry:	06 May 2020	Odometer:	198,481 Kms	Good No:	19861459	Oil level	~		
VIN:	WVWZZZ6NZVW1947	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	S PT SC	-0	S D SC S D SC		S D PT SC	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
						Operation V			<u> </u>
R = rust	mp			10	JHIN	Noise	~		
PT = paint def C = crack	ect			+	S D SC	Clutch	~		
P = pin dent	Ho	KI			JIII —				~
* = decals SDSC QQ						CV joints Wheel bearings	~		
SC = stone chips									
W = significant scuffs S SC S D PT S D SC S D						Brakes			
		N				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		Ļ
Clear coat coming off LF door ,						Tyres (lowest observed tread depth of tyres)			
						Left front	3		mm
						Right front		3 m	
						Left rear		7 mn	
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,modified wiring to th	ne battery ,minor	underneath body sur	face rust ,		Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	wear and t	tear,minor stains	,			Head lights	~		
	hood linin	g coming off ,				Tail lights	~		
Carpets						Indicators	~		
Panels	gear stick	handle broken,st	ereo surround broken	,		Dashboard warning lights	~		
	ignition m	odified to push h	outton and switch ,			Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Ignition modified has a on/off switch and push button start,hood lining coming off ,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		L
Road Conditions During Test Drive: Dry						Central locking	~		
		<u> </u>				Remote locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	+		~
Evidence of Cam Belt Replacement: Yes Kms: 150,313						Reversing camera			~
	•			_					
Inspected by: Donovan Matara Date: 08 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: