
Basic Vehicle Condition Guide

Report ID: 19,862,153
Version: 1
Created: 10 Nov 2019

Make:	Ford	**Model:**	Fiesta	**Body Style:**	Hatchback
Year:	2007	**Registration:**	EBW137	**Reg Expiry:**	12 Aug 2020
WoF Expiry:	30 Jun 2020	**Odometer:**	146,948 Kms	**Good No:**	19862153
VIN:	WF0HXXGAJH7L6476(	**Next Service:**		**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Headlights faded

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Drive belt and pulley noisy
Engine vibration
AC not getting cold

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt
Evidence of Cam Belt Replacement: No **Kms:**

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch	✔		
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	4 mm		
Right front	4 mm		
Left rear	4 mm		
Right rear	4 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation		✔	
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Xinghui Lin Date: 10 Nov 2019

I have read and understood this condition guide. Name: ..... Signature: .....