# Turners

## Basic Vehicle Condition Guide

Report ID: 19,862,499
Version: 2
Created: 17 Nov 2019

| | | | |
|---|---|---|---|
| **Make:** Fiat | **Model:** 500 | **Body Style:** Hatchback | |
| **Year:** 2009 | **Registration:** MFA828 | **Reg Expiry:** 03 Aug 2020 | |
| **WoF Expiry:** 22 Aug 2020 | **Odometer:** 54,687 Kms | **Good No:** 19862499 | |
| **VIN:** ZFA31200000358528 | **Next Service:** 62.757 | **Service History:** Yes | |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

S    SC    P SC    S
SC
SC
P    S

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments
Good

**Conditions During Body Inspection:** Dry

### Under Carriage & Under Bonnet Inspection Comments
Good
Slight transmission oil seepage

### Interior Comments

| Seats | Good |
|---|---|
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

### General Comments
Good

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable    **Kms:**

| | Pass | Fail | N/A |
|---|:---:|:---:|:---:|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 7.0 | mm | |
| Right front | 7.0 | mm | |
| Left rear | 8.0 | mm | |
| Right rear | 8.0 | mm | |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | | | ✔ |
| Window winder RR | | | ✔ |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | ✔ | | |
| Number of keys | 2 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | | | ✔ |

**Inspected by:** Jeremy Hutchings    **Date:** 11 Nov 2019

I have read and understood this condition guide.    Name: .......................................................    Signature: ...........................................