


| | | |
|---------------------|--------------------------------------|--------------------------------|
| Make: Nissan | Model: Navara | Body Style: Utility |
| Year: 1993 | Registration: ZP4439 | Reg Expiry: 05 Feb 2020 |
| WoF Expiry: | Odometer: 367,000 Not Appical | Good No: 19862729 |
| VIN: | Next Service: due | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
 S = scratch
 D = dent
 R = rust
 PT = paint defect
 C = crack
 P = pin dent
 * = decals
 SC = stone chips
 W = significant scuffs



Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram

Front tyres worn
 Rust in body
 Rust under body
 Vehicle in poor condition need further checks

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clutch slipping
 Shocks soft
 Play front hubs
 Service due
 No wof
 Brake vibration

Interior Comments

| | |
|-----------|------|
| Seats | Poor |
| Carpets | Poor |
| Panels | Poor |
| Dashboard | Poor |

General Comments

Play in door hinges
 Oil leaks
 Coolant leaks
 Oil low

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt
 Evidence of Cam Belt Replacement: No Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | | ✓ | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | | ✓ | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | ✓ | | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | | ✓ | |
| CV joints | | | ✓ |
| Wheel bearings | | ✓ | |
| Brakes | | | |
| Performance | | ✓ | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 0.0 | mm | |
| Right front | 0.0 | mm | |
| Left rear | 3.0 | mm | |
| Right rear | 3.0 | mm | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | | ✓ | |
| Steering performance | | ✓ | |
| Shock absorbers | | ✓ | |
| Air Conditioning / Heater | | | |
| Operation | | | ✓ |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | ✓ | | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 2 | | |
| Central locking | ✓ | | |
| Remote locking | | | ✓ |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Jeff Luke Date: 14 Nov 2019

I have read and understood this condition guide. Name: Signature: