

Report ID: 19,863,805 Version: 1 11 Nov 2019 Created:

Make:	Mitsubishi	Model:	L300	Body Style:	Van		Pass	Fail	N/A
Year:	2011	Registration:	FYE65	Reg Expiry:	01 Feb 2020	Engine	1		I
WoF Expiry:	21 Oct 2020	Odometer:	229,199 Kms	Good No:	19863805	Oil level	~		
VIN:	JMAHNP14VBA80036	Next Service:	237000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	ort is not a warranty	anation is maada	for one and miles	o Dorto hovo rot	heen discontined or	Noise	~		
diagnostic test	a guide only. Conside ting undertaken. The	vehicle has beer	driven up to 50km/	h from cold. The	/endor recommends	Cooling System			
a full mechanio	cal inspection prior to	purchase and the	his can be arranged i	for an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD SD	201-	SD	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			X	Transmission	•		
D = dent	s sc w				EIN SW	Operation	~		
R = rust PT = paint defe					JHIH	Noise	~		
C = crack				+	SC	Clutch	~		
P = pin dent						CV joints			~
* = decals	SDSC 916				ET PS	Wheel bearings	~		•
SC = stone chip	/	VA		20	& <u> </u>	Brakes	•		
W = significant scuffs S D R						Performance			
		Note: som	e defects & blemish	es may not be disn	layed in the diagram	Hand Brake	~		
	ection Comments	1010.3011		es may not be alsp				oftyre))
Drivers door hinges worn						Tyres (lowest observed tread depth of tyres) Left front 7.0 mm			
								-	mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	nage & onder bor	<u>ince inspectie</u>	<u>in comments</u>			Suspension			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation			~
Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboar	d Average					Wipers (front & rear)	~		
	<u> </u>					Window winder FL	~		
						Window winder FR	~		
General Comments Knock coming from front suspension ?					Window winder RL			~	
	ig nom from suspensio	יווט (Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			~
		·				Remote locking			~
Engine Timing Mechanism: Timing Chain					Sat. Nav. (basic test only)			~	
	of Cam Belt Replac	ement: N	lot Applicable	Kms:					~
Evidence o						Reversing camera			
Evidence o				1.113.		Date: 11 Nov 20	10		•

I have read and understood this condition guide.

Name:

Signature: