

Basic Vehicle Condition Guide

Report ID: 55,164


Version: 1

Created: 15 Nov 2019

Make: Model: Toyota Aurion **Body Style:** Sedan Year: 2008 Registration: FJQ880 Reg Expiry: 11 Feb 2020 **WoF Expiry: Odometer:** 10 Jul 2020 258,812 Kms **Good No:** 19865844 VIN: **Next Service:** 6T153KK400X300892 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	ОК		
Carpets	ОК		
Panels	ОК		
Dashboard	ОК		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

11 Nov 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A	
Engine			1	
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System	•		•	
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	V			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		4	mm	
Right front		4	mm	
Left rear		5	mm	
Right rear		5	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors				
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1			
Central locking	'			
Remote locking	~			
Sat. Nav. (basic test only)			'	
Reversing camera			'	

Signature: