

Report ID: 19,866,244 Version: 2 13 Nov 2019 Created:

Make:	Mitsubishi	Model:	Airtrek	Body Style:	SUV		Pass	Fail	N/A	
Year:	2002	Registration:	GYF643	Reg Expiry:	06 Apr 2020	Engine				
WoF Expiry:		Odometer:	267,146 Kms	Good No:	19866244	Oil level	~			
VIN:	7AT0CJ3FX11011371	Next Service:		Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		с I I	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	SP W	-0	SRP SD		S D R	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent SCW SPTW						Operation 🖌				
R = rust PT = paint defect						Noise	~			
C = crack					R SC	Clutch			~	
P = pin dent						CV joints	~		•	
* = decals SRSC 919 SDPT						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SD W SD SD SD W SD W						Performance	~			
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	() ()	
Right taillight cracked Rear Badge missing									 	
One chip windscreen inside CVA						Right front			 mm	
One chip windscreen outside CVA Headlights cracked						Left rear		-		
					Right rear			mm		
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Remote no	-	•				Suspension performance		~		
Engine oil leak Front inner CV boots leaking grease						Steering performance	~	•		
Front inner	CV boots leaking greas	e				Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Seats driver seat worn					Head lights	~			
						Tail lights	•	~		
Carpets	Average					Indicators	~	-		
Panels	Average					Dashboard warning lights	~			
Faileis						Wipers (front & rear)	~			
Dashboa	rd Average					Window winder FL	~			
						Window winder FR	~			
General (<u>Comments</u>					Window winder RL	~			
Squeaking rear suspension						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	· · · · · · · · · · · · · · · · · · ·			
	uning les		Dry			Remote locking	-	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)		-	~	
Evidence of Cam Belt Replacement: Yes Kms: 203,878 Reversing camera									~	
Inspected by: Kyle Mills-Brown Date: 13 Nov 2019										

I have read and understood this condition guide.

Name:

Signature: