

Basic Vehicle Condition Guide

Report ID: 19,868,077

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 08 Dec 2019

Fail

N/A

1

mm

mm

mm

 mm

3.0

3.0

5.0

5.0

1

/

/

/

1

1


2

Yes

Make: Model: Toyota Harrier **Body Style:** Wagon Year: 2004 Registration: MJJ648 **Reg Expiry:** 15 Jan 2020 **WoF Expiry: Odometer:** 15 Nov 2020 105,312 Kms **Good No:** 19868077 VIN: 7AT0H634X15007102 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comment | <u>S</u> |
|------------------|----------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

2wd

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

| ave read and understood this condition guide. | Name: | Signature: | |
|---|-------|-----------------------------|----|
| Inspected by: Bobby Zhong | | Date: 16 Nov 20 | 19 |
| evidence of Cam Belt Replacement: No | Kms: | Reversing camera | |
| engine riming Mechanism: Cambeil | | Sat. Nav. (basic test only) | |