

Report ID: 19,868,650 Version: 1 19 Nov 2019 Created:

Make:	Honda	Model:	Stream	Body Style:	SUV		Pass	Fail	N/A
Year:	2001	Registration:	DHF836	Reg Expiry:	01 Dec 2019	Engine			L
WoF Expiry:	14 Nov 2020	Odometer:	199,368 Kms	Good No:	19868650	Oil level	~		
VIN:	7A88GAD0706056567	Next Service:	15/05/20	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for and milaana	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC S	-0	SP SD		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	EII S	Operation	~		
R = rust PT = paint defe				$\prod$	JHIH	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	PT SC 916				EIIP I	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	Note: Joh		indy not be disp	ayea in the diagram		•	oftyre	
						Tyres (lowest observed tread depth of tyres)   Left front 6.0 m			
						Right front			mm
						Left rear	6.		mm
			_				6.		
Conditions During Body Inspection: Dry						Right rear			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	ak from right side of end		<u>eonnents</u>			Suspension			
	ak nonninght side of eng	gine.				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	Good					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Ganaral						Window winder FR	~		<u> </u>
<u>General Comments</u> Door light pin on left front door is broken & sometimes door light on dash display will not go out. Mirror is						Window winder RL	~		<u> </u>
broken & not fitting in correctly in left side wing mirror & shakes around. ###Correct kms are 199,340kms###.						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engine Th	ming Machanism	T: (	- 			Remote locking			~
-	ming Mechanism:	Timing (		<b>V</b> acation		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspector	d by: Jason Young					Date: 15 Nov 20	19		
	a sy. sason roung					Dute. 15100/20			

I have read and understood this condition guide.

Name: .....

Signature: .....