

Basic Vehicle Condition Guide

Report ID: 19,869,322


Version: 3

Created: 18 Mar 2020

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2014 Registration: HJR710 Reg Expiry: 14 Apr 2020 WoF Expiry: **Odometer:** 11 Oct 2020 230,156 Kms **Good No:** 19869322 VIN: 6G1NN5E47EL974544 Next Service: 240,000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



•

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive

| Interior Comment | <u>s</u> |
|------------------|----------|
| Seats | Average |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

| Genera | Comments |
|--------|----------|
| | |

LPG

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Mathew Varghese Date:

Name:

| /A |
|---------------------------------------|
| |
| |
| |
| |
| , , , , , , , , , , , , , , , , , , , |
| , , , , , , , , , , , , , , , , , , , |
| |
| |
| , , — |
| , , |
| , , |
| , , |
| , , |
| , |
| n |
| |
| |
| n |
| n |
| n |
| |
| n |
| n |
| n |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

18 Mar 2020

Signature: