

Report ID: 19,870,776 Version: 1 Created: 21 Nov 2019

Make:	Ford	Model:	Laser	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1995	Registration:	EMW718	Reg Expiry:	19 Jan 2020	Engine			
WoF Expiry:		Odometer:	221,861 Kms	Good No:	19870776	Oil level	~		
VIN:	7A5AAASAPMST7402		221,001 1(11)	Service Histor		Smoke & fumes	~		
	77(5)(0)(5)(1)(5)(1)(5)(7)(6)2.				. 110	Performance	~		
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	V		L
	ical inspection prior to					Coolant condition	~		1
		_				Performance	~		
Key:	P SC	-0	SP P		P SC	Radiator / Hoses (visual)	~		
S = scratch	Se	20		10/2	X	Transmission	V		
D = dent	s sc all				HID S				1
R = rust				10	VHIK	Operation	~		
PT = paint defe	ect				P SC	Noise	~		<u> </u>
C = crack P = pin dent	LH			-		Clutch			~
* = decals	P SC DC				Ella	CV joints	~		<u> </u>
SC = stone chi	ps U	10		10		Wheel bearings	~		
W = significant scuffs						Brakes			
	PT SC	N	S D PT SC S SC		P SC	Performance	~		<u> </u>
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Clearcoat coming off vehicle. Stonechips on windscreen.						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyre		
AC not cold. Heater fan noisy. Glovebox catch broken, cannot open. RF window not opening. LR and RR seatbelts have wear. Parcel tray missing. Boot board is cracked. RF seat and seatbelt have wear. Stereo not						Left front	Left front 2		
	ave wear. Parcel tray mis ation memory.	ssing. Boot board	d is cracked. RF seat an	d seatbelt have v	vear. Stereo not	Right front		2	mm
. etag st						Left rear		1	mm
Condition	ns During Body Ins	pection:	Dry			Right rear	4	1	mm
Conditions During Dody inspection. Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Coolant add	ditive concentration bel	low manufacture	ers recommended leve	l, suggest coolan	t change. Engine	Suspension performance	~		1
has oil leaks						Steering performance	~		
LF tyre has	outer edge wear.					Shock absorbers	~		+
						Air Conditioning / Heater	•		
						Operation		~	1
Interior Comments						Electrical / Accessories		V	
	Average					Head lights			T
Seats							~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	, we have					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
<u> </u>						Window winder FR		~	
<u>General Comments</u>					Window winder RL	~			
Automatic transmission has noise in reverse. Spare tyre is flat.					Window winder RR	~			
						Rear view mirrors	~		
Drives ok.						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking			~
						Remote locking			~
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 10	94,000	Reversing camera			~
	-								
Inspected	d by: Roger King					Date: 21 Nov 20	19		
I have read a	and understood th	is condition a	uide. Name: .			Signature:			