

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance SP Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent Operation V R = rustNoise V PT = paint defect D C = crackClutch 1 P = pin dent V CV joints * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs D Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 **Right front** 5.0 mm Left rear 3.0 mm **Right rear** 3.0 mm Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats V Tail lights 1 Good Carpets Indicators ~ Average Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V General Comments Window winder RL 1 Audio not working Window winder RR V Rear view mirrors 1 Radio (basic test only) 1 CD (basic test only) ~ Number of keys 2 Central locking V **Road Conditions During Test Drive:** Dry Remote locking V **Engine Timing Mechanism: Timing Chain** Sat. Nav. (basic test only) V Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera ~ 23 Jan 2020 Inspected by: Dante Dacanay Date:

I have read and understood this condition guide.

Name:

Signature:

Report ID: 19,873,158 Version: 4 Created: 29 Jan 2020

Pass

~

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

Fail