

Basic Vehicle Condition Guide

Report ID: 19,873,444

Version:


Created: 25 Nov 2019

Fail N/A

Make: Model: Jeep Renegade **Body Style:** SUV Year: 2017 Registration: LCA643 Reg Expiry: 13 Dec 2019 **WoF Expiry: Odometer:** 12 Dec 2020 23,222 Kms **Good No:** 19873444 VIN: 1C4BU0000HPF64170 Next Service: 26000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

/

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Name:

Engine			
Oil level	~		
Smoke & fumes	~		
Performance	v		
Noise	~		
Cooling System		•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	>		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	3	.0	mm
Left rear	5.0 mr		mm
Right rear	6.0 mm		
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories		1	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \) \(\t		
Wipers (front & rear)	~		
Window winder FL			
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

Reversing camera

25 Nov 2019

Signature:

Inspected by:	Chris Buckley	Dat