



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,873,779
Version:	1
Created:	20 Nov 2019

Make:	Subaru	Body Style:	Wagon
Model:	Impreza	VIN:	7AT0GF09X19002012
Year:	2006	Odometer:	53,867 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79	Sun Roof Operation	•	
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80	Front Windscreen (no chips)	Good	
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	
4	High Stop Light	✓	Transmission and Drive		Suspension		82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	34	Operation	✓	58	Suspension Performance	✓	83	Front Wiper Blades	Good	
6	Front Left Indicators	✓	35	Noise	✓	59	Steering Performance	✓	84	Rear Wiper Blade	Good	
7	Rear Right Indicators	✓	36	Clutch	•	60	Shock Absorbers	✓	85	R/H Mirror	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	Wheels and Tyres		86	L/H Mirror	Good		
9	Reversing Lights	✓	38	Wheel Bearing	✓	61	Left Front	4.0	mm	87	L/F Guard	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	62	Right Front	4.0	mm	88	R/F Guard	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	✓	63	Left Rear	4.0	mm	89	L/H Doors	Good
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	64	Right Rear	4.0	mm	90	R/H Doors	Good
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	No	65	Spare	Yes	91	L/H Sill	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		66	Tools	✓	92	R/H Sill	Good	
15	Number Plate Light	✓	Brakes		Interior		67	AC Operation	✓	93	Boot/Tail Gate	Good
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	94	Front Bumper	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	95	Rear Bumper	Good	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	96	Roof	Good	
19	Rev Counter	✓	Keys and Locking		71	Seat Heaters	•	97	Bonnet	Good		
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	98	Fuel Cap	✓	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓	
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Good	100	WOF	✓	
23	Window Opener FR	✓	Engine		75	Carpets	Good					
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Good				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Good				
26	Rear View Mirrors	✓	52	Performance	✓							
27	Radio (Basic Test Only)	✓	53	Noise	✓							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓							
29	Boot Open Switch	✓										

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	20 Nov 2019
---------------	-------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--