

Report ID: 19,875,512 Version: 1 10 Dec 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2009	Registration:	FEN591	Reg Expiry:	23 Jul 2020	Engine	1		1
WoF Expiry:	07 May 2020	Odometer:	126,119 Kms	Good No:	19875512	Oil level	~		
VIN:	KL3JA695JAK569467	Next Service:	131500	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S SC S P SC		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	E S	Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIG				세비	CV joints	~		-
* = decals	SPSC 91			- Jul	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S D SC S D SC S D SC S S SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	layed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		of tvre	es)
Drivers door mirror casing needs paint ,						Left front 3 mm			
						Right front		, <u>2</u>	 mm
						Left rear		<u>-</u> }	mm
Candition		n a ati a n .	D.			Right rear			 mm
Conditions During Body Inspection: Dry						Right rear 3 mn Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Good Good						Head lights	~		
						Tail lights	~		
Carpets	Good						~		
Panels	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	ard Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RE	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Deed Canditions During Test Driver a						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Ti	ming Mechanism:	Unknow	'n			Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:									v
		P				Reversing camera			~
Inspected by: Donovan Matara Date: 10 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: