



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,875,622
Version:	1
Created:	17 Dec 2019

Make:	Honda	Body Style:	Hatchback
Model:	FIT	VIN:	7AT08G2YX19007410
Year:	2014	Odometer:	95,937 Kms
Road Conditions During Test Drive:	Wet		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good				
1	Battery	✓	31	Reversing Camera	✓	56	Performance	✓	79	Sun Roof Operation		✗						
2	Headlights	✓	32	USB Port	✓	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good							
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good					
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good					
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓</th> <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	60	Shock Absorbers	✓	83	Front Wiper Blades	Good							
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	3.5	mm	84	Rear Wiper Blade	Good				
7	Rear Right Indicators	✓	37	CV Joints	✓	62	Right Front	3.5	mm	63	Left Rear	4.0	mm	85	R/H Mirror	Good		
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	64	Right Rear	4.0	mm	65	Spare	N/A	66	Tools	✓	86	L/H Mirror	Good
9	Reversing Lights	✓	39	Wheel Balance	✓	41		Engine Timing	Timing Chain	87	L/F Guard	Good	88	R/F Guard	Good			
10	Rear Reflectors	✓	40	Gearbox (Manual)	✓	42		Evidence of Cam Belt Replacement	Not Applicable	89	L/H Doors	Good	90	R/H Doors	Good			
11	Hazard Lights	✓	43	Replaced at (odometer reading)		43		Replaced at (odometer reading)		91	L/H Sill	Good	92	R/H Sill	Good			
12	Courtesy Lights	✓	Brakes		44	Front Brakes	✓ <td>45</td> <td>Rear Brakes</td> <th>✓<td>93</td><td>Boot/Tail Gate</td><td>Good</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	45	Rear Brakes	✓ <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	93	Boot/Tail Gate	Good	94	Front Bumper	Good		
13	Dashboard Lights	✓	46	Handbrake	✓	Keys and Locking		47	Central Locking	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	95	Rear Bumper	Good	96	Roof	Good		
14	Dashboard Dimmer Switch	✓	Brakes		48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>97</td> <td>Bonnet</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	49	Number of Keys	1	97	Bonnet	Good	98	Fuel Cap	✓		
15	Number Plate Light	✓	Brakes		49	Number of Keys	1	Engine		50	Oil Level	✓ <td>99</td> <td>Mud Flaps</td> <th>✓</th>	99	Mud Flaps	✓			
16	Dashboard Warning Lights	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>53</td><td>Noise</td><th>✓<td>100</td><td>WOF</td><th>✓</th></th></th>	52	Performance	✓ <td>53</td> <td>Noise</td> <th>✓<td>100</td><td>WOF</td><th>✓</th></th>	53	Noise	✓ <td>100</td> <td>WOF</td> <th>✓</th>	100	WOF	✓				
17	Speedo	✓	54	Starter Motor	✓ <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td>													
18	Odometer	✓																
19	Rev Counter	✓																
20	Fuel Gauge	✓																
21	Wipers Front/Rear	✓																
22	Window Opener FL	✓																
23	Window Opener FR	✓																
24	Window Opener RL	✓																
25	Window Opener RR	✓																
26	Rear View Mirrors	✓																
27	Radio (Basic Test Only)	✓																
28	CD (Basic Test Only)	✓																
29	Boot Open Switch	✓																

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Xinghui Lin	Date:	24 Nov 2019
---------------	-------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--