

Basic Vehicle Condition Guide

Report ID: 19,878,454


Version: 2

Created: 06 Jan 2020

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2005 Registration: CND126 Reg Expiry: 17 Sep 2020 WoF Expiry: **Odometer: Good No:** 03 Jan 2021 123,691 Kms 19878454 VIN: 6G1ZL54B75L395593 Next Service: 137970 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dion Mair Date: 05 Dec 2019

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	5.0		mm	
Right front	5.0		mm	
Left rear	8		mm	
Right rear	8		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	V V V V V V V			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR				
Rear view mirrors	V			
Radio (basic test only)				
CD (basic test only)	~			
Number of keys	2	1		
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature: