



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,879,088
Version:	1
Created:	11 Dec 2019

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	VIN:	7AT0GF09X19002913
Year:	2007	Odometer:	98,774 Kms
Road Conditions During Test Drive:	Dry		

Electrical			30	Fuel Flap Release		✓
1	Battery	✓	31	Reversing Camera		•
2	Headlights	✓	32	USB Port		•
3	Tail Lights	✓	33	Window Lock Switch		✓
4	High Stop Light	✓	Transmission and Drive			
5	Front Right Indicators	✓	34	Operation		✓
6	Front Left Indicators	✓	35	Noise		✓
7	Rear Right Indicators	✓	36	Clutch		•
8	Rear Left Indicators	✓	37	CV Joints		✓
9	Reversing Lights	✓	38	Wheel Bearing		✓
10	Rear Reflectors	•	39	Wheel Balance		✓
11	Hazard Lights	✓	40	Gearbox (Manual)		•
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	No	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		
15	Number Plate Light	✓	Brakes			
16	Dashboard Warning Lights	✓	44	Front Brakes		✓
17	Speedo	✓	45	Rear Brakes		✓
18	Odometer	✓	46	Handbrake		✓
19	Rev Counter	✓	Keys and Locking			
20	Fuel Gauge	✓	47	Central Locking		✓
21	Wipers Front/Rear	✓	48	Remote Locking		✓
22	Window Opener FL	✓	49	Number of Keys	2	
23	Window Opener FR	✓	Engine			
24	Window Opener RL	✓	50	Oil Level		✓
25	Window Opener RR	✓	51	Smokes and Fumes		✓
26	Rear View Mirrors	✓	52	Performance		✓
27	Radio (Basic Test Only)	✗	53	Noise		✓
28	CD (Basic Test Only)	✗	54	Starter Motor		✓
29	Boot Open Switch	✓				
Cooling System			55	Coolant Condition		✓
			56	Performance		✓
			57	Radiator/Hoses (visual)		✓
Suspension			58	Suspension Performance		✓
			59	Steering Performance		✓
			60	Shock Absorbers		✓
Wheels and Tyres			61	Left Front	7.0 mm	
			62	Right Front	7.0 mm	
			63	Left Rear	7.0 mm	
			64	Right Rear	6.5 mm	
			65	Spare	Yes	
			66	Tools		✓
Interior			67	AC Operation		✓
			68	Heater Fan		✓
			69	Seatbelts		✓
			70	Horn		✓
			71	Seat Heaters		•
			72	Sun Visors		✓
			73	Sun Visors Lights/Mirrors		✓
			74	Seats	Good	
			75	Carpets	Good	
			76	Panels	Good	
			77	Dashboard	Good	
Exterior			78	Under Carriage	Good	
			79	Sun Roof Operation	•	
			80	Front Windscreen (no chips)	Good	
			81	Back Windscreen (no chips)	Good	
			82	Side Windows (no chips)	Good	
			83	Front Wiper Blades	Good	
			84	Rear Wiper Blade	Good	
			85	R/H Mirror	Good	
			86	L/H Mirror	Good	
			87	L/F Guard	Good	
			88	R/F Guard	Good	
			89	L/H Doors	Good	
			90	R/H Doors	Good	
			91	L/H Sill	Good	
			92	R/H Sill	Good	
			93	Boot/Tail Gate	Good	
			94	Front Bumper	Good	
			95	Rear Bumper	Good	
			96	Roof	Good	
			97	Bonnet	Good	
			98	Fuel Cap	✓	
			99	Mud Flaps	✓	
			100	WOF	✗	

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Mathew Varghese	Date:	26 Nov 2019
---------------	-----------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--