# Turners

## Basic Vehicle Condition Guide

Report ID: 19,879,602
Version: 3
Created: 20 Mar 2020

| | | | |
|---|---|---|---|
| **Make:** Ford | **Model:** Mondeo | **Body Style:** Hatchback | |
| **Year:** 2007 | **Registration:** EBK551 | **Reg Expiry:** 09 Jul 2020 | |
| **WoF Expiry:** 22 Jun 2020 | **Odometer:** 183,155 Kms | **Good No:** 19879602 | |
| **VIN:** WF05XXGBB56G8535 | **Next Service:** 187,000 | **Service History:** No | |

**Note: This report is not a warranty**
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Diagram labels: S, W, P, D, W, S, S, SC, PT SC, W, S, S, W

Note: some defects & blemishes may not be displayed in the diagram

### Body Inspection Comments
Windscreen stone chips

### Conditions During Body Inspection: Dry

### Under Carriage & Under Bonnet Inspection Comments
Front wheel drive

### Interior Comments

| | |
|---|---|
| Seats | Average |
| Carpets | Floor mats missing x2 |
| Panels | Average |
| Dashboard | Good |

### General Comments
Drives ok.

### Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain
**Evidence of Cam Belt Replacement:** Not Applicable     Kms:

| | Pass | Fail | N/A |
|---|:---:|:---:|:---:|
| **Engine** | | | |
| Oil level | ✔ | | |
| Smoke & fumes | ✔ | | |
| Performance | ✔ | | |
| Noise | ✔ | | |
| **Cooling System** | | | |
| Coolant condition | ✔ | | |
| Performance | ✔ | | |
| Radiator / Hoses (visual) | ✔ | | |
| **Transmission** | | | |
| Operation | ✔ | | |
| Noise | ✔ | | |
| Clutch | | | ✔ |
| CV joints | ✔ | | |
| Wheel bearings | ✔ | | |
| **Brakes** | | | |
| Performance | ✔ | | |
| Hand Brake | ✔ | | |
| **Tyres** (lowest observed tread depth of tyres) | | | |
| Left front | 6.5 | | mm |
| Right front | 6 | | mm |
| Left rear | 2.5 | | mm |
| Right rear | 2.5 | | mm |
| Spare | Yes | | |
| **Suspension** | | | |
| Suspension performance | ✔ | | |
| Steering performance | ✔ | | |
| Shock absorbers | ✔ | | |
| **Air Conditioning / Heater** | | | |
| Operation | ✔ | | |
| **Electrical / Accessories** | | | |
| Head lights | ✔ | | |
| Tail lights | ✔ | | |
| Indicators | ✔ | | |
| Dashboard warning lights | ✔ | | |
| Wipers (front & rear) | ✔ | | |
| Window winder FL | ✔ | | |
| Window winder FR | ✔ | | |
| Window winder RL | ✔ | | |
| Window winder RR | ✔ | | |
| Rear view mirrors | ✔ | | |
| Radio (basic test only) | ✔ | | |
| CD (basic test only) | ✔ | | |
| Number of keys | 1 | | |
| Central locking | ✔ | | |
| Remote locking | ✔ | | |
| Sat. Nav. (basic test only) | | | ✔ |
| Reversing camera | | | ✔ |

Inspected by: Roger King

Date: 20 Mar 2020

I have read and understood this condition guide.     Name: ...................................     Signature: ...................................