

Report ID: 19,881,381


Version: 3

Created: 19 Dec 2019

| Make: | Holden | Model: | Captiva 7 | Body Style: | SUV |
|-------------|-------------------|---------------|------------|-----------------|---------------|
| Year: | 2011 | Registration: | FUW472 | Reg Expiry: | 28 Jul 2020 |
| WoF Expiry: | 24 Dec 2020 | Odometer: | 97,990 Kms | Good No: | 19881381 |
| VIN: | KL3CD266JBB027880 | Next Service: | 107,900kms | Service History | y: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD

| <u>Interior Comments</u> | | | | | |
|--------------------------|---------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Good | | | | |
| Panels | Average | | | | |
| Dashboard | Good | | | | |

General Comments

Road Conditions During Test Drive: Dry

Timing Chain Engine Timing Mechanism:

Evidence of Cam Belt Replacement: Not Applicable Kms:

17 Dec 2019 Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|---------------------------------------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 7 | .0 | mm |
| Right front | 7 | .0 | mm |
| Left rear | 6 | .0 | mm |
| Right rear | 6 | .0 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | V V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ! | ļ | 1 |
| Operation | ~ | | |
| Electrical / Accessories | I | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | \(\times \) \(\t | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | <u> </u> | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | V |
| Reversing camera | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| eversing camera | | | |

Signature: