

Basic Vehicle Condition Guide

Report ID: 19,882,744


Version: 2

Created: 30 Nov 2019

Make: Model: Volkswagen **Passat Body Style:** Wagon Year: 2006 Registration: KYZ582 Reg Expiry: 12 Apr 2020 **Odometer:** WoF Expiry: 08 Sep 2020 128,487 Kms **Good No:** 19882744 VIN: WVWZZZ3CZ7E06094 Next Service: 124000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil overfill

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Good | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

General Comments

AWD

Engine noisy need further investigation

Sunroof not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 29 Nov 2019

| | Pass | Fail | N/A | |
|------------------------------|-----------------|---------|-----|--|
| Engine | | | | |
| Oil level | | ~ | | |
| Smoke & fumes | ~ | | | |
| Performance | ~ | | | |
| Noise | | ~ | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | v | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 4 | .0 | mm | |
| Right front | 4.0 | | mm | |
| Left rear | 4.0 | | mm | |
| Right rear | 5.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | \(\triangle \) | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |
| | | | | |

I have read and understood this condition guide.

Name:

Signature: