

Report ID: 19,884,097 Version: 4 18 May 2020 Created:

Make:	Toyota	Model:	Vitz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2001	<b>Registration:</b>	DKA650	<b>Reg Expiry:</b>	16 Oct 2020	Engine		1	
WoF Expiry:	23 Aug 2020	Odometer:	283,791 Kms	Good No:	19884097	Oil level		~	
VIN:	7A8H63E0706262934	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance		~	
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and u	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
	S SC		S D SC S D SC		S D SC	Performance	~		
Key: S = scratch		=		5(0)-	5550	Radiator / Hoses (visual)	~		
						Transmission			
R = rust	SDCSC			20	S C SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					S	Clutch	~		
P = pin dent	SDSC DR				74Hb	CV joints	~		
* = decals		10		10	S D SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S SC	C	S P SC S P SC		S D PT SC	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	2	.0	mm
						Right front	1	1.5 m	
						Left rear	1	.0	mm
Conditions During Body Inspection: Dry						Right rear	1.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						uspension			
Engine blov	wing a big end bearing					Suspension performance	~		
						Steering performance	~		
Shock absorbers						~			
						Air Conditioning / Heater			
						Operation			~
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	front floor	carpets ripped ,				Tail lights	~		
			ala an interit a t			Indicators	~		
Panels	there are s	ome broken par	els on interior trims,			Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL		~	
Concert	ammarta					Window winder FR	~		
LF tyre flat ,	<u>Comments</u>					Window winder RL	~		
Le tyre lidt,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Dry							~		
Enging Ti	ning Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism:   Timing Chain     Evidence of Cam Belt Replacement:   Not Applicable   Kms:     Reversing camera									~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 09 Mar 2020									

I have read and understood this condition guide.

Name: .....

Signature: .....