

Basic Vehicle Condition Guide

Report ID: 19,886,598


Version: 1

Created: 02 Dec 2019

Make: Model: Rover 214 SI **Body Style:** Hatchback Year: 1997 Registration: WR9595 Reg Expiry: 03 Feb 2020 WoF Expiry: **Odometer:** 07 Apr 2020 142,574 Kms **Good No:** 19886598 VIN: SAXXWSWEBAD37983 Next Service: 147,000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Hood lining loose

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak Under body oxidation

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Date: 02 Dec 2019

	Pass	Fail	N/A
Engine	•		
Oil level	~		
Smoke & fumes	~		
Performance	\(\triangle \)		
Noise	~		
Cooling System	•	•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tvre	L es)
Left front		.5	mm
Right front	6.3		mm
Left rear	6.6		mm
Right rear	6.9		mm
Spare	Yes		
Suspension		103	
Suspension performance	V		
Steering performance	~		
Shock absorbers	<i>y</i>		
Air Conditioning / Heater			
Operation			V
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	<i>'</i>		
Window winder FL	~		
Window winder FR	~		
Window winder RL			
Window winder RR	V		
Rear view mirrors	V		
Radio (basic test only)	<i>V</i>		
CD (basic test only)	_		
Number of keys	2		
Central locking	~		
Remote locking			-
Sat. Nav. (basic test only) Reversing camera			'

I have read and understood this condition guide.

lan Dunn

Name:

Kms:

Signature: