

Report ID: 19,886,719 Version: 2 16 Dec 2019 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail	N/A
Year:	2006	Registration:		Reg Expiry:	01 Jan 2020	Engine	I	l	
WoF Expiry:		Odometer:	133,999 Kms	Good No:	19886719	Oil level	~		
VIN:	7AT08G7HX12101501	Next Service:	144000	Service Histor	y: No	Smoke & fumes	~	L	
						Performance	~		
	port is not a warranty	oration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition	~		
					Р	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent R = rust	SC DE			715	HIL S	Operation	~		
PT = paint defe	ect NP	F I		$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					P SC	Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals	sc 916			-No-	ALC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	t scuffs w				S D	Performance	~		
Body Incr	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	s)
W/Screen chip left side lower,									mm
						Right front	5.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm
conditions bailing body inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Surface Rus	t on under body of veh	icle .				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Chris Buckley Date: 02 Dec 2019									
Inspected by. Chris buckley Date: 02 Dec 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....