

Basic Vehicle Condition Guide

Report ID: 19,886,774

Version: 2

Engine

Created: 30 Jan 2020


Fail

N/A

Make: Model: Skoda Octavia **Body Style:** Sedan Year: 2013 Registration: **GRT571** Reg Expiry: 29 Apr 2020 WoF Expiry: **Odometer: Good No:** 17 Dec 2020 155,530 Kms 19886774 VIN: TMBCT61Z3D2093918 Next Service: 165,000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Oil level	~			
Smoke & fumes	~			
Performance	\(\times \)			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed treac	l depth	of tyre	:s)	
Left front	4	.1	mm	
Right front	5.5 mm			
Left rear	3.7		mm	
Right rear	4.5 mm			
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	\(\triangle \)			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	V V V V V			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			,	

Signature:

02 Dec 2019 Inspected by: lan Dunn

Name: