

Report ID: 19,886,828 Version: 1 06 Dec 2019 Created:

Make:	Ford	Model:	Focus	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	GCS348	Reg Expiry:	07 Nov 2020	Engine			
WoF Expiry:	02 May 2020	Odometer:	128,783 Kms	Good No:	19886828	Oil level	~		
VIN:	WF0PXXWPDPBD1821	Next Service:	137000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC	-161-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC S S						Operation	~		
PT = paint defe				$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	110				세비	CV joints	~		
* = decals	sc 916			The	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
D. L.L.		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front	3.		mm
						Left rear	2.		mm
Conditions During Rody Inspection:						Right rear	2.		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil low	-	·				Suspension performance	~		
Minor oil le	ak					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
raneis						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Vibration through vehicle, possibly engine mount						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		I
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	-								_ <b>*</b>
Inspected by: Dion Mair Date: 06 Dec 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....