

Report ID: 19,943,167 Version: 2 05 Mar 2020 Created:

Make:	Hyundai	Model:	130	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	ERF743	Reg Expiry:	18 Jan 2020	Engine			•
WoF Expiry:	31 Jan 2021	Odometer:	175,576 Kms	Good No:	19943167	Oil level	~		
VIN:	KMHDC51TR8U11784	Next Service:	182000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
			PT S PT		S D	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	PT SC			710	EIIVS	Operation	~		
PT = paint defe	ect NP	r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	INTER HIP				7414	CV joints	~		
* = decals	PT SC 91			-Jos		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	t scuffs S		D PT			Performance	~		
Body Incr	Position Commonts	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front	6.	.0	mm	
						Right front	6.	.0	mm
						Left rear	6.	-	mm
Conditions During Body Inspection: Dry						Right rear		6.0 m	
Conditions During Body inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor Engii	ne oil leaks					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2 1		
Road Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	•		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			
									~
Inspected by: Bobby Zhong Date: 07 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: