

Report ID: 19,945,139 Version: 1 Created: 07 Dec 2019

Make:	Citroen	Model:	C5	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2001	Registration:		Reg Expiry:	20 Dec 2020	Engine			
WoF Expiry:	19 Dec 2020	Odometer:	217,402 Kms	Good No:	19945139	Oil level	~		
VIN:	VF7DCRFNC76131637			Service Histor		Smoke & fumes	~		
			,			Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:	PT SC	-0	PT P SC	-M-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT SC			The	SPT	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				$+ \vee$		Clutch	~		
P = pin dent	HID				세비	CV joints	~		
* = decals	PT SC 916			- NL	ELD SPT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S PT P S						Performance	~		
Dealerteen	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inst	pection Comments			, ,	, ,	Tyres (lowest observed tread	d depth	of tyre	es)
								mm	
						Right front	-	.0	mm
						Left rear		.4	mm
Condition	as During Body Insi	pection:	Day			Right rear		.6	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
Left rear door is not locking with central locking. Right rear electric door window is not working.						Window winder RR		~	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking		~	
						Remote locking	~		
-	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 06 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: