

Report ID: 19,956,978 Version: 1 17 Dec 2019 Created:

Make:	Mitsubishi	Model:	Diamante	Body Style:	Sedan		Pass	Fail	N/A
Year:	2003	Registration:	BFP651	Reg Expiry:	14 Jan 2020	Engine	I	I	1
WoF Expiry:	08 Apr 2020	Odometer:	195,543 Kms	Good No:	19956978	Oil level		~	
VIN:	6MMTJ9X422T056682	Next Service:	195000	Service Histor	y: Yes	Smoke & fumes		~	
						Performance	~		
	port is not a warranty	oration is made	for and mileage	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	SP		PT P	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect						Operation	~		
						Noise	~		
C = crack				$+ \vee$	РТ Р	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals PT SC 919 S D PT						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W SP SP W S						Performance			
		Note: son	he defects & blemishe	s may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre))
Bonnet stays need Regas, R/F Door Handle Damaged ,					Tyres (lowest observed tread depth of tyres) Left front 1.0 mm				
									mm
						Right front	1.0		mm
					Left rear		.0	mm	
Conditions During Body Inspection: Dry						Right rear	5.0		mm
Under Carriage & Under Bonnet Inspection Comments					Spare Yes				
Oil leak lower engine area, Surface Rust on underbody of Vehicle.						Suspension			
	er engine area, surface	Rust on underbit	buy of vehicle.			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation		~	
Poor						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Δ					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking		V	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
ц								1	1
Inspected by: Chris Buckley Date: 17 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: