

## **Basic Vehicle Condition Guide**

Report ID: 19,956,997

Pass

~

~

/

1

1

/

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of kevs

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 28 Feb 2020

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

9.0

9.0

3.0

3.0

1

/

/

1

/

1

1


2

Yes

Make: Model: Great Wall V-Series **Body Style:** Utility Year: 2014 Registration: HNP766 **Reg Expiry:** 17 Apr 2020 WoF Expiry: **Odometer:** 03 Dec 2020 61,363 Kms **Good No:** 19956997 VIN: LGWCB3171EB625157 Next Service: 71,286kms **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Right fog light cracks

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Rear wheel drive

<u>Interior Comments</u>				
Seats	Average			
Carpets	Good			
Panels	Average			
Dashboard	Good			

_		
Genera	l Com	ments

**Road Conditions During Test Drive:** Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** 

	Central locking	V			
	Remote locking 🗸				
	Sat. Nav. (basic test only)		~		
Kms:	Reversing camera		V		
Date: 23 Dec 2019					
Name: Signature:					

Inspected by: Mathew Varghese	
I have read and understood this condition guide.	Name: