

Report ID: 19,962,022 Version: 2 08 Jan 2020 Created:

Signature:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2017	Registration:	BJTYRE	Reg Expiry:	28 Sep 2019	Engine	1		·
WoF Expiry:	22 Jan 2021	Odometer:	62,958 Kms	Good No:	19962022	Oil level	~		
VIN:	MPATFR85JHT001192	Next Service:	72,944kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	* D*	-01-	D*	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	- HE			715	HIL S	Operation	~		
PT = paint defe				$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints			~
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan			* *		*	Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front		;	mm
						Right front	4.	5	mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Underbody	rattles					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		·
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
-	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
la se estad har. Ce Theah									
Inspected by: Ca Thach Date: 08 Jan 2020									

I have read and understood this condition guide.

Name: