

Basic Vehicle Condition Guide

Report ID: 19,963,037

Version:

Engine

Created: 24 Dec 2019

Pass


Fail

N/A

Make: Model: V50 Volvo **Body Style:** Wagon Year: 2005 Registration: KEM73 Reg Expiry: 13 Aug 2020 WoF Expiry: **Odometer: Good No:** 22 Nov 2020 87,591 Kms 19963037 VIN: YV1MW664952093087 Next Service: ? **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Cd player is not working.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Jason Young

Evidence of Cam Belt Replacement: No

Kms:

Oil level	'		
Smoke & fumes	<i>v</i>		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	6	.8	mm
Right front	6.5		mm
Left rear	7.0		mm
Right rear	7.0		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)		~	
Number of keys	1	-	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			'

I have read and understood this condition guide.

Name:

Signature:

23 Dec 2019

1

Reversing camera