

Report ID: 19,970,540 Version: 1 23 Jan 2020 Created:

Make:	Suzuki	Model:	Grand Vitara	Body Style:	SUV		Pass	Fail	N/A
Year:	2011	Registration:	FWN863	Reg Expiry:	18 Jul 2020	Engine	1		
WoF Expiry:	26 Nov 2020	Odometer:	133,188 Kms	Good No:	19970540	Oil level	~		
VIN:	JSAJTDA4V00224756	Next Service:	143168	Service Histor	y: No	Smoke & fumes	~		+
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
	SC		P SC	S		Performance	~		
Key:	La C	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			710	BUSDC	Operation	~		
PT = paint defe	ect NP				101h	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	I SPEC HIP				2414	CV joints	~		
* = decals	SPSC 91			To .	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S SC S		SD SD			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)			es)
						Left front	5 mm		
						Right front	5	5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	<		
Comoto	Good					Tail lights	~		
Carpets						Indicators	<		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
	iiu					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	<		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	• • • •	 /	-			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
		2				Data 22 las 201			
Inspected	d by: Donovan Matar	u				Date: 23 Jan 202			

I have read and understood this condition guide.

Name:

Signature: