



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,975,219
Version:	1
Created:	17 Jan 2020

Make:	Honda	Body Style:	Sedan
Model:	Accord	VIN:	7AT08G13X19303589
Year:	2007	Odometer:	89,206 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good		
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation		•				
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	80	Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td>	81	Back Windscreen (no chips)	Good			
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th>	59	Steering Performance	✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td>	82	Side Windows (no chips)	Good			
5	Front Right Indicators	✓	35	Noise	✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th>	60	Shock Absorbers	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good					
6	Front Left Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front	7.0	mm	84	Rear Wiper Blade	Good		
7	Rear Right Indicators	✓	37	CV Joints	✓ <td>62</td> <td>Right Front</td> <td>6.0</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>7.0</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td>	62	Right Front	6.0	mm	63	Left Rear	7.0	mm	85	R/H Mirror	Good
8	Rear Left Indicators	✓	38	Wheel Bearing	✓ <td>64</td> <td>Right Rear</td> <td>7.0</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	64	Right Rear	7.0	mm	65	Spare	Yes	86	L/H Mirror	Good	
9	Reversing Lights	✓	39	Wheel Balance	✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td>	66	Tools	✓	87	L/F Guard	Good					
10	Rear Reflectors	✓	40	Gearbox (Manual)	✓ <th colspan="2">Interior</th> <td>67</td> <td>AC Operation</td> <th>✓<td>88</td><td>R/F Guard</td><td>Good</td></th>	Interior		67	AC Operation	✓ <td>88</td> <td>R/F Guard</td> <td>Good</td>	88	R/F Guard	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good		
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>90</td> <td>R/H Doors</td> <td>Good</td>	71	Seat Heaters	•	90	R/H Doors	Good		
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>91</td> <td>L/H Sill</td> <td>Good</td>	91	L/H Sill	Good		
14	Dashboard Dimmer Switch	✓	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td>	74	Seats	Good	92	R/H Sill	Good			
15	Number Plate Light	✓	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th>	46	Handbrake	✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	75	Carpets	Good	93	Boot/Tail Gate	Good		
16	Dashboard Warning Lights	✓	Keys and Locking		47	Central Locking	✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Good	94	Front Bumper	Good			
17	Speedo	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>3</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td>	49	Number of Keys	3	77	Dashboard	Good	95	Rear Bumper	Good		
18	Odometer	✓	Engine		50	Oil Level	✓ <td>78</td> <td>Seats</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td>	78	Seats	Good	96	Roof	Good			
19	Rev Counter	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td>79</td><td>Carpets</td><td>Good</td><td>97</td><td>Bonnet</td><td>Good</td></th>	52	Performance	✓ <td>79</td> <td>Carpets</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td>	79	Carpets	Good	97	Bonnet	Good		
20	Fuel Gauge	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>80</td><td>Panels</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th>	54	Starter Motor	✓ <td>80</td> <td>Panels</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th>	80	Panels	Good	98	Fuel Cap	✓		
21	Wipers Front/Rear	✓							81	Dashboard	Good	99	Mud Flaps	✓		
22	Window Opener FL	✓							82			100	WOF	✗		
23	Window Opener FR	✓							83							
24	Window Opener RL	✓							84							
25	Window Opener RR	✓							85							
26	Rear View Mirrors	✓							86							
27	Radio (Basic Test Only)	✗							87							
28	CD (Basic Test Only)	✗							88							
29	Boot Open Switch	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>89</td> <td></td> <td></td> <td></td> <td></td> <td></td>							89							

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Chris Buckley	Date:	15 Jan 2020
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--