

Make:	BMW	Model:	Х3	Body Style:	SUV		Pass	Fail	N/A
Year:	2009	Registration:	HMH732	Reg Expiry:	08 Jul 2020	Engine	I		L
WoF Expiry:	30 Jan 2021	Odometer:	129,459 Kms	Good No:	19980323	Oil level	~		
VIN:	WBAPC72070WG6150	Next Service:	135,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		D SC D	S		Performance	~		
Key:	13 UL	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust S A A S S S S S S S S S S S S S S S S						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
*=decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – significan	W		D	S		Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
						Left front	4 m		mm
						Right front	2	ļ	mm
						Left rear	4	ł	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Four wheel	drive					Suspension performance	~		
						Steering performance	~		
		Shock absorbers	~						
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	<		
Carpets						Indicators	<		
Panels	Good					Dashboard warning lights	~		
Deckler	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	<		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Dante Dacanay Date: 27 Feb 2020									
Inspected by: Dante Dacanay Date: 27 Feb 2020									

I have read and understood this condition guide.

Name:

Signature: