

## **Turners Certified 100 Point Check**

## Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,981,812
Version:	2
Created:	03 Jul 2020

Make:	Suzuki	Body Style:	Hatchback TSMEXB32S00211863		
Model:	Splash	VIN:			
Year:	2010	Odometer:	58,437 Kms		
Road Conditions During Test Drive:	Dry				

Ele	ectrical	30	Fuel Flap Release		Coc	oling System			Ext	erior		
1	Battery	31	Reversing Camera •		55	Coolant Condition			78	Under Carriage	Good	
2	Headlights	32	USB Port •		56	Performance			79	Sun Roof Operation		
3	Tail Lights	33	Window Lock Swi	Window Lock Switch		Radiator/Hoses (visual)			80	Front Windscreen (no chips)	Good	
4	High Stop Light	Tra	nsmission and D	rive	Sus	spension			81	Back Windscreen (no chips)	Good	
5	Front Right Indicators	34	Operation		58	Suspension Performance			82	Side Windows (no chips)	Good	
5	Front Left Indicators	35	Noise		59	Steering Performance			83	Front Wiper Blades	Good	
7	Rear Right Indicators	36	Clutch		60	Shock Absorbers			84	Rear Wiper Blade	Good	
8	Rear Left Indicators	37	CV Joints		Wh	neels and Tyres			85	R/H Mirror	Good	
9	Reversing Lights	38	Wheel Bearing		61	Left Front	4.0	mm	86	L/H Mirror	Good	
10	Rear Reflectors	39	Wheel Balance		62	Right Front	5.0	mm	87	L/F Guard	Good	
11	Hazard Lights	40	Gearbox (Manual)		63	Left Rear	5.0	mm	88	R/F Guard	Good	
12	Courtesy Lights	41	Engine Timing	Timing Chain	64	Right Rear	3.0	mm	89	L/H Doors	Good	
13	Dashboard Lights	42	Evidence of Cam Belt Replacement	Not Applicable	65	Spare	Yes		90	R/H Doors	Good	
14	Dashboard Dimmer Switch	43	Replaced at (odometer reading)		66	Tools		91	L/H Sill	Good		
15	Number Plate Light	Bra	Brakes			erior			92	R/H Sill	Good	
16	Dashboard Warning Lights	44	Front Brakes		67	AC Operation			93	Boot/Tail Gate	Good	
17	Speedo	45	Rear Brakes		68	Heater Fan •			94	Front Bumper	Good	
18	Odometer	46	Handbrake		69	Seatbelts			95	Rear Bumper	Good	
19	Rev Counter	Key	ys and Locking		70	Horn			96	Roof	Good	
20	Fuel Gauge	47	Central Locking		71	Seat Heaters •		97	Bonnet	Good		
21	Wipers Front/Rear	48	Remote Locking	X	72	Sun Visors		98	Fuel Cap	V		
22	Window Opener FL	49	Number of Keys	1	73	Sun Visors Lights/Mirrors		99	Mud Flaps			
23	Window Opener FR	Eng	gine		74	Seats	Good	l	100	WOF	>	
24	Window Opener RL	50	Oil Level		75	Carpets	Good					
25	Window Opener RR	51	Smokes and Fumes		76	Panels	Avera	age				
26	Rear View Mirrors	52	Performance		77	Dashboard	Good	l	•			
27	Radio (Basic Test Only)	53	Noise						Turners Certification Key:			
28	CD (Basic Test Only)	54 Starter Motor						√ = Pass				
29	Boot Open Switch						<ul><li>×= Fail</li><li>= Not applicable for this vehicle</li></ul>					

Inspected by: Chris Buckley Date: 16 Jan 2020

I have read and understood this condition guide:

Name: Signature: