



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,982,050
Version:	2
Created:	18 Feb 2020

Make:	Subaru	Body Style:	Wagon
Model:	Exiga	VIN:	7AT0GF1RX20007471
Year:	2009	Odometer:	115,526 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good	
4	High Stop Light	✓	Transmission and Drive		Wheels and Tyres		59	Steering Performance	✓	60	Shock Absorbers	✓	85	R/H Mirror	Good		
5	Front Right Indicators	✓	34	Operation	✓	61	Left Front	7.0	mm	62	Right Front	7.0	mm	86	L/H Mirror	Good	
6	Front Left Indicators	✓	35	Noise	✓	63	Left Rear	7.0	mm	64	Right Rear	7.0	mm	87	L/F Guard	Good	
7	Rear Right Indicators	✓	36	Clutch	•	65	Left Rear	7.0	mm	66	Right Rear	7.0	mm	88	R/F Guard	Good	
8	Rear Left Indicators	✓	37	CV Joints	✓	67	Left Rear	7.0	mm	68	Right Rear	7.0	mm	89	L/H Doors	Good	
9	Reversing Lights	✓	38	Wheel Bearing	✓	69	Left Rear	7.0	mm	70	Right Rear	7.0	mm	90	R/H Doors	Good	
10	Rear Reflectors	•	39	Wheel Balance	✓	71	Left Rear	7.0	mm	72	Right Rear	7.0	mm	91	L/H Sill	Good	
11	Hazard Lights	✓	40	Gearbox (Manual)	•	73	Left Rear	7.0	mm	74	Right Rear	7.0	mm	92	R/H Sill	Good	
12	Courtesy Lights	✓	41	Engine Timing	Cambelt	75	Left Rear	7.0	mm	76	Right Rear	7.0	mm	93	Boot/Tail Gate	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Yes	77	Left Rear	7.0	mm	78	Right Rear	7.0	mm	94	Front Bumper	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)	92,861	79	Left Rear	7.0	mm	80	Right Rear	7.0	mm	95	Rear Bumper	Good	
15	Number Plate Light	✓	Brakes		Interior		81	Left Front	7.0	mm	82	Right Front	7.0	mm	96	Roof	Good
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	83	Left Front	7.0	mm	84	Right Front	7.0	mm	97	Bonnet	Good	
17	Speedo	✓	45	Rear Brakes	✓	85	Left Front	7.0	mm	86	Right Front	7.0	mm	98	Fuel Cap	✓	
18	Odometer	✓	46	Handbrake	✓	87	Left Front	7.0	mm	88	Right Front	7.0	mm	99	Mud Flaps	✓	
19	Rev Counter	✓	Keys and Locking		89	Left Front	7.0	mm	90	Right Front	7.0	mm	100	WOF	✗		
20	Fuel Gauge	✓	47	Central Locking	✓	91	Left Front	7.0	mm	92	Right Front	7.0	mm				
21	Wipers Front/Rear	✓	48	Remote Locking	✓	93	Left Front	7.0	mm	94	Right Front	7.0	mm				
22	Window Opener FL	✓	49	Number of Keys	2	95	Left Front	7.0	mm	96	Right Front	7.0	mm				
23	Window Opener FR	✓	Engine		97	Left Front	7.0	mm	98	Right Front	7.0	mm					
24	Window Opener RL	✓	50	Oil Level	✓	99	Left Front	7.0	mm	100	Right Front	7.0	mm				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	101	Left Front	7.0	mm	102	Right Front	7.0	mm				
26	Rear View Mirrors	✓	52	Performance	✓	103	Left Front	7.0	mm	104	Right Front	7.0	mm				
27	Radio (Basic Test Only)	✓	53	Noise	✓	105	Left Front	7.0	mm	106	Right Front	7.0	mm				
28	CD (Basic Test Only)	✓	54	Starter Motor	✓	107	Left Front	7.0	mm	108	Right Front	7.0	mm				
29	Boot Open Switch	✓				109	Left Front	7.0	mm	110	Right Front	7.0	mm				

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Ca Thach	Date:	12 Jan 2020
I have read and understood this condition guide:			
Name:		Signature:	